



GTS INFINITY

Ref: GA/bw
August 8th, 2001

CDC / Vessel Sanitation Program
1850 Eller Drive, Suite 101
Fort Lauderdale, FL, 33316
USA

Dear Sir

INFINITY – VESSEL SANITATION INSPECTION REPORT
CORRECTIVE ACTION TAKEN

The following actions have been taken to correct each of the deficiencies noted during the inspection of Infinity on August 8th, 2001 in the port of Ketchikan.

Item No.	Deficiency	Corrective Action
1	Oceanview Café, Port / Stbd. Several bowls of nuts, seeds, raisins, shredded coconut, dates, jelly and brown sugar were on display for passenger self-service outside of the installed sneeze shield.	New sneeze shields were installed.
2	Oceanview Café, Port / Stbd. Several trays filled with breads and danish were displayed on the center buffet sections for passenger's self service with no sneeze shields in place.	New sneeze shields were installed.
3	Oceanview Café, Port / Stbd. Sneeze shields were not installed on the end sections of the buffets or the center near the bread toasting operation.	New sneeze shields are required. Miami Office is dealing.
4	Oceanview Café, Port / Aft. Cold-top trays of sliced cheese, pickled herring and sliced turkey on display for passenger self-service had product temperatures of 50°F. Sliced cheese at the port / fwd. Buffet line was also at 50°F.	Food handlers were strongly advised to keep food within safe temperature zone.
5	Oceanview Café, Stbd. A soiled and wet wiping cloth was sitting on a buffet counter between uses.	Food handlers and food personnel were advised on the correct cleaning procedures.
6	Oceanview Café, Bar Grill.	Screw fasteners were replaced for non-slot head

	The rotisserie wheel screw fasteners had difficulty cleaning slot heads.	one.
7	Oceanview Café, Bar Grill. The ends of the buffet were not provided with sneeze shields.	New sneeze shields are required. Miami Office is dealing.
8	Oceanview Café, Pot Wash. Several dirty pans were stored on deck stands, as there was not one dirty rack stand in the area for dirty pots, pans and utensils. Two large pans were filled with water to soak and stored on a deck stand only one inch away from the clean storage rack.	Personnel in the area were trained to use proper pallets and to avoid mixing dirty/clean utensils.
9	Oceanview Café, Dishwash. Several dishware racks were stored on the deck between uses, as were some dirty trays.	Personnel in the area were trained to use proper pallets and to avoid mixing dirty / clean utensils.
10	Oceanview Café, Dishwash. Entry and exit for this space was from outside, unscreened doors, ensure there is some method for flying insect control at these doorways.	Miami Office is investigating.
11	Fun Factory Child Center. The child toilet seat was not child size.	Guarantee # was issued.
12	Fun Factory Child Center. There was no sign posted in the child toilet room advising providers to wash their hands and the Children's' hands after assisting children using the toilet.	Signs were posted.
13	Dining Room Pantry, Deck 4. Light fixture was broken due to entrance door hitting it.	Light fixture was replaced and a stopper was placed to avoid hitting.
14	Galley, Deck 3. The blast chiller had been out of order for three weeks.	Guarantee #E197 is outstanding. Our Technical Department is putting pressure for a quick solution.
15	Appetizer Pantry, Deck 3. The blade for the floor chopper was heavily soiled with food residue.	Food personnel was additionally trained and explained why equipment should be cleaned, spotless, after use.
16	Bell Box, Deck 8. The interior of the small microwave was cracked.	New microwave has been requested. Requisition order 57000614.IN3 has been placed.
17	Bell Box Pot Wash. An employee was observed sanitizing equipment in the 3 compartment sink for about 5 seconds.	Employee was trained on the correct procedure of three-compartment sink washing.

- | | | |
|----|--|--|
| 18 | Integrated pest Management (IPM).
The IPM did not include: 1) Provisions for active monitoring including pest sighting logs for the operational areas of the vessel, or 2) passive surveillance procedures such as glue traps and other monitoring tools. | Our pest control company provided the glue traps on Friday, August 17 th , 2001 and monitoring log is maintained. |
| 19 | Thalassotherapy Pool, Deck 10.
Recommend that the free chlorine residual be maintained between 3:00m and 5:00pm. | No action. |

Sincerely,

Captain G. Andrianatos
Master
GTS Infinity
Celebrity Cruises